

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1068  
NE  
> 1  
1.409 mi.  
7441 ft.

SOIL  
2286 EAST 12TH ST  
BROOKLYN, NY

NY Spills S110611598  
N/A

Relative:  
Higher

Actual:  
13 ft.

SPILLS:

Name: SOIL  
Address: 2286 EAST 12TH ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1007846 / 2010-12-10  
Facility ID: 1007846  
Facility Type: ER  
DER Facility ID: 396322  
Site ID: 441295  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C3  
SWIS: 2401  
Spill Date: 2010-10-25  
Investigator: SFRAHMAN  
Referred To: Not reported  
Reported to Dept: 2010-10-25  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2010-10-25  
Spill Record Last Update: 2010-12-10  
Spiller Name: Not reported  
Spiller Company: RACHEL ARAZI  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: RACHEL ARAZI  
DEC Memo: "10/25/10- Zhune spoke to Rachel Arazi (718-501-1945). She said the oil company came to do a tune up to the boiler and found oil tank leaking from the bottom. She also said leakage is very little coming from botton of tank. She put a paille to collect the oil. They are going going to change the system to gas. Later company is coming to pump out oil from tank. The tank is in the basement. There is no vapors in the house. 11/01/10 csl sent out to Jak Srou 2286 East 12th Street Brooklyn, NY 11223(sr) \*\* csl returned undelivered\*\*.  
Resend to JAK SROUR 1701 OCEAN PKWY BROOKLYN, NY 11223-2048 12/10/10 Spoke with Rachel Arazi.She said the old tank was replaced and no spill occurred from the old tank.Case closed.(sr) "  
Remarks: "Caller advised small active leak from above ground tank onto cement. Spiller is refusing to clean up the spill or fix the leak."  
All Materials:  
Site ID: 441295  
Operable Unit ID: 1191860  
Operable Unit: 01  
Material ID: 2187061  
Material Code: 0001A

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported